



**Engineering, Operations & Technology**  
Boeing Research & Technology

# Non-Cr paint systems on commercial aircraft – current status and future direction

Angela C Davis

(206) 915-7339

[angela.c.davis2@boeing.com](mailto:angela.c.davis2@boeing.com)

<b>Report Documentation Page</b>			Form Approved OMB No. 0704-0188	
<p>Public reporting burden for the collection of information is estimated to average 1 hour per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of this collection of information, including suggestions for reducing this burden, to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Davis Highway, Suite 1204, Arlington VA 22202-4302. Respondents should be aware that notwithstanding any other provision of law, no person shall be subject to a penalty for failing to comply with a collection of information if it does not display a currently valid OMB control number.</p>				
1. REPORT DATE <b>NOV 2014</b>	2. REPORT TYPE	3. DATES COVERED <b>00-00-2014 to 00-00-2014</b>		
4. TITLE AND SUBTITLE <b>Non-Cr paint systems on commercial aircraft - current status and future direction</b>			5a. CONTRACT NUMBER	
			5b. GRANT NUMBER	
			5c. PROGRAM ELEMENT NUMBER	
6. AUTHOR(S)			5d. PROJECT NUMBER	
			5e. TASK NUMBER	
			5f. WORK UNIT NUMBER	
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES) <b>Boeing Research &amp; Technology,Engineering, Operations &amp; Technology,100 North Riverside ,Chicago,IL,60606</b>			8. PERFORMING ORGANIZATION REPORT NUMBER	
9. SPONSORING/MONITORING AGENCY NAME(S) AND ADDRESS(ES)			10. SPONSOR/MONITOR'S ACRONYM(S)	
			11. SPONSOR/MONITOR'S REPORT NUMBER(S)	
12. DISTRIBUTION/AVAILABILITY STATEMENT <b>Approved for public release; distribution unlimited</b>				
13. SUPPLEMENTARY NOTES <b>ASETSDefense 2014: Sustainable Surface Engineering for Aerospace and Defense, 18-20 Nov 2014, Fort Myer, VA.</b>				
14. ABSTRACT				
15. SUBJECT TERMS				
16. SECURITY CLASSIFICATION OF:  a. REPORT      b. ABSTRACT      c. THIS PAGE <b>unclassified</b> <b>unclassified</b> <b>unclassified</b>			17. LIMITATION OF ABSTRACT  <b>Same as Report (SAR)</b>	18. NUMBER OF PAGES  <b>15</b>
				19a. NAME OF RESPONSIBLE PERSON

# Overview

## Boeing Commercial Airplanes

**Cr<sup>6+</sup> Overview**

**Historic & Current use of Cr<sup>6+</sup>**

**Chromate use and alternatives**


**Strategy for Sunset Date**

**Near term systems and qualifications**

**Gaps and long term developments**

# Cr<sup>6+</sup> Overview



Cr<sup>6+</sup> is a known carcinogen and an excellent corrosion inhibitor



Gold Standard of Corrosion Inhibitors

Carcinogenic

- REACH Sunset Date 2017-2019
- Hazardous Waste
- OSHA Permissible Exposure Limit 5 µg/m<sup>3</sup>




# Historic & Current use of Cr<sup>6+</sup> Boeing Commercial Airplanes

Cr<sup>6+</sup> containing materials have been used on all metal parts, including aluminum, titanium, and stainless steel alloys.

Over 75% of the plane is coated with chromated materials.

Successful Cr<sup>6+</sup> reductions via:

- Substrates and Design changes (composite materials, titanium, guidelines, etc.)
- Alternative materials (products and processes)



Item	Division	Sub-division	Surface of part	Location on airplane	Finish requirement
Bare plate and sheet, extruded shapes, extruded bar drawn or rolled bar, forged block, forgings and castings FN 3				Fuselage lower lobe FN 1	Anodize + two coats BMS 10-11 Type I primer
				Fuselage upper lobe	Anodize + BMS 10-11 Type I primer
				Nonaero-dynamic exterior	Anodize + BMS 10-11 Type I primer
				Exterior Aerodynamic	Anodize + BMS 10-79 Type III primer + BMS 10-60 Type II white enamel or BMS 10-126 Type II
				Landing gear	Anodize + BMS 10-79 Type III primer + BMS 10-60 Type II gray enamel
Attached to CFRP FN 8 FN 3		Within 4 in of CFRP FN 54	General except as noted below	General	Anodize + two coats BMS 10-11 Type I primer
				Located in integral fuel tank	Anodize + two coats BMS 10-20 Type II primer
			Exterior Aerodynamic, Wing and empennage trailing edge coves		Anodize + two coats BMS 10-79 Type III primer

Corrosion Potential Table

Group	Metal or alloy
I	Magnesium and its alloys
II	Aluminum, zinc, and their alloys. Cadmium-titanium, cadmium or zinc-nickel plating
III	Steels (except CRES), Iron, lead, tin, and their alloys. Tin plating.
IV	CFRP, titanium and titanium alloys, CRES, bronze (aluminum-bronze or aluminum-nickel-bronze), nickel and nickel alloys, chromium (plating), copper, brass, copper-nickel, copper-beryllium, molybdenum, cobalt alloys, tungsten, carbon, silver, and gold


# Chromate Alternative Successes and Targets

Chromated material/process	Alternatives
Chromic acid anodize	Boric sulfuric acid anodize (BSAA), Accelerated sulfuric acid anodize (ASAA)
Deoxidizers	Ferric/nitric deoxidizers
Paint strippers	Mechanical, benzyl alcohol based. In work: laser & atmospheric plasma
Composite primers	BMS10-103
Exterior primer (BMS10-72, MIL-PRF-23377)	BMS10-72 NC In work: searching for Cr <sup>6+</sup> equivalency
Non-structural interior primer (BMS10-11 Ty I lite)	In work: XBMS10-147
Structural interior primer (BMS10-11 Ty I, MIL-PRF-85582, MIL-PRF-23377)	In work
Bond primer (BMS5-89, BMS5-137)	In work
Assembly level primer	In work
BMS10-20 (SAE-AMS-C-27725)	In work
BMS10-79	In work
BMS5-95	In work


# Strategy for Sunset Date

## Non-Cr for BMS10-11, BMS10-20, BMS10-72/BMS10-79, BMS5-89



### Multidimensional approach:



**Test top candidates to the spec requirements, match product performance to application.**



# Corrosion Protection System Development



## Materials development

- CSIRO, Boeing, Suppliers, universities
- Inhibitor species
- Polymer resins
- Formulation nuances


## Testing/evaluation

- Boeing, universities, CSIRO
- Accelerated exposure protocols
- Advanced evaluation techniques

## Modeling tools

- Boeing, CSIRO, universities
- Inhibitor mechanisms
- Transport processes
- Service performance prediction

# Continuous Screening Overview



## Materials Process Example:



## Test panel stack-ups:

### Detail Primer:

7075-T6 Bare Al
Alodine 600
BSAA Unsealed
BMS10-128

BMS10-11 Ty I Green  
or  
Candidate

### Assembly Primer:

7075-T6 Bare Al
Alodine 600
BSAA Unsealed
BMS10-128

BMS10-11 Ty I Green

BMS10-11 I Yellow  
or  
Candidate


## Screening Tests:

- Dry/Wet Adhesion. BSS7225, ASTM D 714.
- 30 days 120F condensing humidity. BSS7225, ASTM D 714
- 30 day hydraulic fluid soak. BSS7263, ASTM D 714
- 5000 hours in Neutral Salt Spray chamber. BSS7249, ASTM D 714


**Candidates that look good in screening, move to production batch testing**

# Continuous Screening

## Medium/High risk zones



Four candidates are moving to production batch testing to BMS10-11 Ty I, BMS10-20, BMS10-72, & BMS10-79



# XBMS10-147

## Low-corrosion risk zones

### Technical Requirements

- Corrosion resistance criteria based on MIL-PRF-23377, but with a wider scribe.
  - Neutral Salt Spray (NSS) for 2000 hrs, no pitting & minimal oxides within the scribe.
- Compatibility requirement testing based on application



### Opportunities

- Interior payloads primer for non-structural parts (brackets, clips, stow-bin rails, etc...) – All models
- Systems Line Replaceable Units (LRU), such as ducts, valves, pumps, etc...) – 777X

### Status:

- 7 candidates tested, top candidate reformulated for improved adhesion (blisters)
  - Reformulation successful, candidate currently in qual testing

Key Tests	Application: Payloads, Systems, Both	8	7	6	5	4	3	2	1
Spray Properties	Both	TBD	PASS	PASS	MARGINAL	PASS	PASS	FAIL	PASS
Drying Properties	Both	PASS SCREENING	PASS	FAIL	PASS	PASS	PASS	PASS	PASS
Color	Payloads	PASS SCREENING	PASS	PASS	PASS	PASS	PASS	PASS	PASS
Gloss	Payloads	TBD	PASS	FAIL	FAIL	PASS	FAIL	FAIL	PASS
Adhesion	Both	PASS SCREENING	FAIL BLISTERS	PASS	PASS	FAIL	FAIL	MARGINAL	FAIL
Humidity	Both	PASS SCREENING	FAIL BLISTERS	PASS	PASS	FAIL	FAIL	PASS	FAIL
Neutral Salt Fog 2000 hrs	Both	TBD	PASS EXCELLENT!!	PASS ACCEPTABLE	FAIL	PASS GOOD	FAIL	FAIL	FAIL
Fluid Resistance	Both	PASS SCREENING	PASS	FAIL	PASS	PASS	FAIL	PASS	PASS
Rivets & Fasteners Adhesion	Both	PASS SCREENING	FAIL BLISTERS	PASS	--	FAIL	--	FAIL	FAIL




### Compatibility requirements by application:

Materials	Payloads Applications	Both	Systems Applications
Substrates		2000 series bare 7000 series bare 6000 series bare	Al Castings Ti 6Al-4V CRES
Substrate Prep	BSAA Unsealed CAA Unsealed Sol-Gel Alocline 1200	BSAA Sealed CAA Sealed Alodine 600 Alocline 1200	Grit Blast Cd plating, Cr6+ Zn-Ni plating, Cr6+ Zn-Ni plating, Cr3+ TCP (Navy Cr3+)
Fluids		BMS3-11 Fuel Water solvents (MEK)	BMS3-32 Ty II
Primers		BMS10-11 Ty1 Gr A BMS10-11 Ty1 Gr B BMS10-11 Ty1 Gr E BMS10-83 Ty IV	PR-1200 RTV
Topcoats		BMS10-83 Ty II BMS10-83 Ty VII	BMS10-60 TY I BMS10-11 Ty II
Sealants		BMS5-142	BMS5-95 BMS5-45
Adhesives			BAC5010 Ty 60 BAC5010 Ty 70 BAC5010 Ty 89

# XBMS10-147

## Top Candidate



### Curing Solution Reformulation

- 5 candidates screened
- Tested Fresh vs Aged 4 months @ 120F
- Chemistry vs mechanical properties

### Liquid Component Testing

- HPLC
- FTIR
- GPC
- LCMS


### Cured Film Testing

- Rivets/Fasteners Adhesion
- Wet/Dry Adhesion
- 120F Condensing Humidity
- SEM/EDS

### Top re-formulation proceeding to qual

- 1<sup>st</sup> production Batch sprayed Sept 2014

### Curing solution chemistry aging vs cured film adhesion properties




### Curing solution components per reformulation.

candidate	initial	1	2	3	4	5
part	B	B	B	B C	B C	B C
Components						
Adh. Rivets & Fasteners	FAIL	FAIL	FAIL	PASS	FAIL	PASS


Proceed to Qual

### SEM – focused ion beam paint cross-section at 12,500x mag



# Adhesive Bond Primer

## High/Medium/Low risk zones




## Overview

- Two candidates selected based on performance over on titanium/sol-gel and aluminum/PAA substrates
- The desired goal is to find a primer that can do both aluminum and titanium bonding at both 250F and 350F processing temperatures

## Key Tests

- Wide Area Lap Shear - *BSS7202 Type III*
- Metal to Metal Peel - *BSS7206 Class 1, ASTM D 1781*
- Salt Spray – Scribed panels, *ASTM B117*
- Wedge Crack – *BSS7448 ASTM D 3762*

## Qual & Implementation Goals:



Bond Primers are Applied on Variety of Surface Treatments and Alloys

Aluminum	Non-Aluminum: Titanium, Stainless Steel, Nickel
aluminum adherend 2024-T3 bare	titanium adherend Ti-6Al-4V
phosphoric acid anodize	1 - Grit Blast 2 - Grit Blast + NaOH 3 - Etch + NaOH
Bond Primer (0.15-0.40 mil / 6400 nm)	Bond Primer (0.15-0.40 mil / 6400 nm)
Adhesive (film) 10 mil	Adhesive (film) 10 mil
Bond Primer (0.15-4 mil / 6400 nm)	Bond Primer (0.15-4 mil / 6400 nm)
phosphoric acid anodize	1 - Grit Blast 2 - Grit Blast + NaOH 3 - Etch + NaOH
aluminum adherend 2024-T3 bare	titanium adherend Ti-6Al-4V


Legend: Sol-gel (0.002-0.004 mil 50-100nm); thin bond primer layer

## Boeing Specifications:

- BMS 5-89**
- MMS350, Ty III
- MMS307, Type II
- HMS 16-1111, Ty 1
- HMS 16-1278, Ty 1
- BMS 5-137**
- DMS 2002, Ty 3 & 4
- DMS 2169, Ty 1(A)
- SCGMS56033, Class 2

# Electrocoat (e-coat)

## Low corrosion-risk zones




### Process:

- Automated, low waste process which provides uniform paint film thickness.

### Overview:

- Potential use for complex geometries, such as tubes in low corrosion-risk zones
- One candidate has passed screening tests, with varying degrees of corrosion protection depending on metal alloy.

### Plans to acquire a Pilot Coater in 2015



# Gaps & Long Term Developments

## Gaps:

- In-service testing and long term exposure. Will not be accepted until proven in service.
  - 50-100k cycles per commercial aircraft
  - Lifecycle of 20+ years
  - Corrosion observed after 8-10 years in-service for Cr
- Risks associated with unknown failure of primary structure
  - Flight and safety critical components
    - Interaction between corrosion effects and fatigue crack initiation is unknown
- Reliable inspection methods
  - Implement nonchromate systems with increased inspection
  - Understand relationship between corrosion morphology and fatigue initiation/propagation
- Risk based implementation increases manufacturing complexity
  - Ensuring the correct coating system on the correct application

## Current Authorization Needs: List 3 and 4 Chromates

List	Substance	CAS	Identification		Authorisation Dates		REACH Authorization Needed		
			Last Application	Sunset	BCA	BDS	Combined		
3	Ammonium Dichromate	7789-09-5	3/21/2016	9/21/2017	NO	NO	NO		
3	Chrome Trioxide	1833-82-0			YES	YES	YES		
3	Chromic Acid, hydrated forms	7738-94-5 & 13530-68-2			YES	YES	YES		
3	Potassium Chromate	7789-00-6			NO	NO	NO		
3	Potassium Dichromate	7778-50-9			YES	YES	YES		
3	Sodium Chromate	7775-11-3			YES	YES	YES		
3	Sodium Dichromate	7789-12-0 & 10588-01-9			YES	YES	YES		
4	Dichromium tris (chromate)	24613-89-6	7/22/2017	1/22/2019	NO	NO	NO		
4	Pentazinc Chromate Oxtahydroxide	49663-84-5			NO	NO	NO		
4	Potassium hydroxyoctaoxaodizincatedichromate	11103-86-9			YES	YES	YES		
4	Strontium Chromate	7789-06-2			YES	YES	YES		

**BCA Chemical Risk Management is interested in discussing partnering opportunities in the chromate use application process**

### Low-Risk Applications

Easy to inspect

Non-structural

Low risk of corrosion

e.g. Payloads, Systems LRU

e.g. Bond primer for Ti

### Medium-Risk Applications

e.g. Assembly primer

e.g. Bond primer for repair

### High-Risk Applications

Difficult/impossible to inspect

Life of airplane

Structural

High risk of corrosion

e.g. Bond primer for Al

